


1



2



3



Do not apply soldering iron to terminals for longer than 5 seconds

Ne pas appliquer fer à souder aux terminaux pour plus de 5 secondes

Nicht anwendbar lötkolben zu Terminals für länger als 5 Sekunden



No se aplicará hierro de soldar a las terminales durante más de 5 segundos



4



?





Caframo

Caframo Limited  
501273 Grey Road 1  
Georgian Bluffs, ON  
N0H 2T0  
Canada

Toll Free / Sans Frais : 1-800-567-3556  
Tel / Tél : 1-519-534-1080  
www.caframo.com

MIRKMN002 Rev01

Caframo

Motor Replacement Instructions  
for Ecofan and Alcona

Instructions pour kit de rechange  
de moteur pour Ecofan et Alcona



Model  
800CA




Model  
802CA



Model  
T805

Model / Modèle  
800CA 802CA T805



Do not apply soldering iron to terminals for longer than 5 seconds

Ne pas appliquer fer à souder aux terminaux pour plus de 5 secondes

Nicht anwendbar lötkolben zu Terminals für länger als 5 Sekunden

No se aplicará hierro de soldar a las terminales durante más de 5 segundos

